



Call the indicated branch  
for current pricing and availability.  
01 = Mentor, 02 = Cincy, 03 = Taylor,  
04 = Pittsburgh, 06 = Evansville  
Perry, NAPP = North Atlantic

**STATUS CODES**  
A = READY  
B = IN PROCESS  
C = "AS IS"

3/10/2009

**TWIN DISC PTO**

ITEM	SPEC # PART #	MODEL	DESCRIPTION	PRICE	MPDF	NCRF	BRANCH	STATUS CODE	SO#
1	R15325	C107A2RG5	2:1 REDUCTION SAE #5	0	0	0	2	C	25980
2	R38443	C110HP4		650	400	70	3	A	
3	RCX110P407	C110HP4	SOLID MOLDED PLATE BALL BRG. COLLAR	650	400	70	2	A	26379
4	RSP111P301	SP111HP3	306 BRG SOLID PLATE	750	400	70	6	A	
5	RSP111P323	SP111HP3	EXTENDED SHAFT	750	400	150	6	A	
6	R36315	SPE111HPS	SELL OUT RIGHT	0	0	0	2	C	26439
7	R38867	SP211HP2	SPECIAL FOR CAT	900	SELL OUTRIGHT	0	1	A	3 UNITS
8	R35966	SP211HP3	SOLID PLATES 306 BRG	900	750	0	1	A	
9	R39712	IBF214OP1	SOLID PLATE 309 BRG	2,700	950	0	3	A	
10	RIB314P109	IBF314OP1	SOLID MOLDED PLATE 307 BRG.	3,300	1,500	0	6	A	
11	RIB314P112	IBF314P1	SOLID MOLDED PLATE 307 BRG.	3,300	1,500	0	2	C	
12	RIB314P119	IBF314	SOLID MOLDED PLATE LESS PILOT BEARING	3,300	1,500	0	2	A	
13	RIB318P010	IB318OP0	SOLID PLATE 309 BRG	6,500	3,500	550	2	A	
14	RIB321P901	IB321OP00	SINTERED PLATES 312 BRG	0	0	0	2	A	
15	R38409	HYDRAULIC PTO	SAE 'C' 4 BOLT DRAWING # XA7512A	1,800	1,000	150	2	A	25959

2) The Published NCRF (Non-Core Return Fee) is billed if core unit is not returned or is a different specification or model arrangement from originally supplied.

3) MPDF on the returned unit will be determined upon disassembly and inspection by Great Lakes Power Products. The following are considered "Major Parts Damage Fee"

Bell Housing    Rear Bearing Carrier    Clutch Shaft

1) The returned exchange unit core is the property of Great Lakes Power. It must be intact, free of cracked or broken housings.

### POWER SHIFT TRANSMISSION (FUNK & TWIN DISC)

ITEM	SPEC # PART #	MODEL	DESCRIPTION	EXCH. PRICE	MPDF	NCRF	BRANCH	STATUS CODE	SO#
1	R4151	12000	MISSING CONVERTER MAY PART OUT	4,000	2,000	500	2	C	25248
2	R6065A	I013E13	DISASSEMBLED	6,000	2,000	1,920	2	C	3306
3	R11439B	1023E110B		6,250	2,500	2,100	2	C	26080
4	R3947	1024E11	ROBBED DRIVE PLATE	6,250	2,500	2,100	2	C	25387
5	R4510	1024E13	S/N 7633 ROBBED OUTPUT YOKE	6,250	4,500	2,750	2	C	24838
6	R4510B	1024E13	MISSING PARTS; DISASSEMBLED	6,250	4,500	2,750	2	C	3319
7	R8361	1024E13	MISSING PARTS; DISASSEMBLED	6,250	4,500	2,750	2	C	3321
8	CRYZ14225B	2233E13DB		8,500	5,000	3,000	4	CORE	J
9	R10133C	2263E130B	S/N 8510002713	8,500	5,000	3,000	2	C	25725
10	R11099A	2363R00DB	GRADALL SPEC	8,500	5,000	3,000	2	C	2336
11	R10852A	236E130B	GRADALL SPEC	8,500	5,000	3,000	2	C	2373
12	RYZ13978A	2263E13NB	2000 SERIES LONG DROP	8,500	5,000	3,000	6	C	
13	CR10610C	2263E13NB	PART OUT	8,500	5,000	3,000	6	C	
14	R9639E	4013EPFA	JEFFREY DRESS APP.	5,000	2,000	1,400	2	C	25482
15	R9639E	4013EPFA	JEFFREY DRESS APP.	5,000	2,000	1,400	2	A	23427
16	R9639E	4013EPFA	JEFFREY DRESS APP.	5,000	2,000	1,400	6	C	
17	YZ15632D	DF2524E000	DF250 PARTS ONLY	0	0	0	2	C	
18		F20E13GB	GRADALL SPEC	3,500	1,500	625	2	C	2335
19	R4791	HMD23125CD		0	0	0	6	A	
20	R99753	TAC-51-2007	SEE CR99752	0	0	0	6	C	
21	R62663	TD51-1109	CORE MISSING PARTS	8,500	3,500	0	2	C	2362
22	R63942	TD-51-1109	CORE MISSING PARTS	8,500	3,500	0	2	C	2363
23	CR61556	TD 41 1103	RUNNING TAKEOUT	8,500	3,500	0	2	C	WG1037
25	CR61556	TD 41 1103	RUNNING TAKEOUT	0	0	0	2	C	WG1039

#### POWER SHIFT TRANSMISSION CORE POLICY

- 1) The returned exchange unit core is the property of Great Lakes Power. It must be intact, free of cracked or broken housings.
- 2) The Published NCRF (Non- Core Return Fee) is billed if core is not returned, or is different from originally supplied unit.
- 3) The MPDF (Major Parts Damage Fee) will be determined upon disassembly and inspection by Great Lakes Power Products. The following are considered Major Components.

Transmission Main Case   Clutch Shafts   Aluminum Components   Missing Parts

### CLUTCHES

ITEM #	SPEC # PART #	MODEL	DESCRIPTION	SELL \$	CORE CHG	BR.	STATUS CODE	SO#	AT:
1	RX205408	17"OC	3 STAGE CONVERTER CLUTCH	2,079	500	ALL	CK STK	N/A	23-1-6
2	RX205408E	17"OC	3 STAGE CONVERTER CLUTCH	2,079	500	ALL	CK STK	N/A	23-1-6
3	RX205408Q	17" OC	3 STAGE CONVERTER CLUTCH	2,320.00	500	ALL	CK STK	N/A	23-1-6
4	RSP318C003	SP318	SPECIAL H&B PLATE CAT	3,200.00	1,000	1	A		61-8-3
5	R29548	PO314	MISSING PARTS; DISASSEMBLED	0	0	2	C	25601	78-2-1

**THE CLUTCHES AVAILABLE ARE LISTED ABOVE AND WILL VARY. \*CORE CREDITS ARE RECEIVED ON 17" OVER CENTER CLUTCHES WHEN CORES ARE RECEIVED, REGARDLESS OF CONDITION.**



GREAT LAKES POWER COMPANIES